

# MONUMENT RECORD

CORNER I.D.

M - 21


STATE OF INDIANA - COUNTY OF MONROE

SECTION 26 27, TOWNSHIP 8 NORTH, RANGE 2 WEST

## MONUMENT DESCRIPTION & REMARKS

PIPE PLACED FLUSH IN ROAD. IT WAS NOT CHECKED TO NORTH OR  
SOUTH, BUT WAS CHECK-CHAINED TO EAST AND WEST 2642.64'  
TO SE CORNER OF SW $\frac{1}{4}$ .

### RECOVERY TIE DRAWING



(•) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, \_\_\_\_\_ HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS \_\_\_\_\_ DAY OF \_\_\_\_\_, 19\_\_\_\_ A.D.

SPACE  
RESERVED  
FOR  
RECORDING  
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. \_\_\_\_\_

OR \_\_\_\_\_

UNITED STATES GOVERNMENT AGENCY

TITLE

TOWNSHIP:  
VAN BUREN

CORNER I.D.

M - 21

# 28

# 26

# 34

NW,NW

NE,NW

NW,NE

NE,NE

SW,NW

SE,NW

SW,NE

SE,NE

NW,SW

NE,SW

NW,SE

NE,SE

SW,SW

SE,SW

SW,SE

SE,SE

2642.64

Van Bu-m21

AZIMUTH and BEARING DATUM DESCRIPTION

DATE 10-24-74 SURVEY PARTY T. Daugherty - H. SUDBURY

COMMENTS Pipe placed flush in Road E - it was not checked to North or South, but was check-chained to East & West  
2642.64 Feet to SE corner of SW 1/4

REFERENCE SKETCH ( use back if ness.)

